Cedar-Thom
Superior Ranger District
Lolo National Forest
Alternative 5

Map 2 - 4

1 Miles

Marble Point
Inventoried Roadless Area

Sheep Mountain - Stateline
Inventoried Roadless Area

Meadow Creek - Upper North Fork
Inventoried Roadlss Area

T 17 N R 27 W
T 17 N R 26 W
T 16 N R 27 W
T 16 N R 28 W
T 16 N R 26 W
T 15 N R 28 W
T 15 N R 27 W

Superior

Legend

- Cedar-Thom Boundary
- Mineral County Structures
- Roads
- Roads Outside Project Boundary
- Trails
- Streams
- Inventoried Roadless Areas
- NonForest Service Ownership

Other Proposals

- Culvert Replacement
- Culvert Removal
- Temporary Bridge
- Rehabilitate Ford Crossing
- Rehabilitate Historic Railroad Grade
- Stream Area Rehabilitation

Road Travel Management

- Changed From Open to Closed Yearlong

Road Treatments

- Decommission
- Long-term Storage
- Long-term Specified Road Construction
- Temporary Road Construction

Vegetation Treatments

- Timber Harvest
- Non-commercial Mechanical Treatments
- Prescribed Burning - Mixed Severity
- Prescribed Burning - Low Severity
- Slash and Pile for Fuels Reduction
- Slash and Pile for Fuels Reduction

Trail Proposals

- Trailhead Relocation
- Trailhead Improvement
- Trail Construction - Non-motorized
- Change From Open to Closed for Motorized Use

The Forest Service uses the most current and complete data available. GIS data and product accuracy may vary. They may be: developed from sources of differing accuracy; accurate only at certain scales, based on modeling or interpretation, incomplete while being created or revised, etc. Using GIS products for purposes other than those for which they were created, may yield inaccurate or misleading results. The Forest Service reserves the right to correct, update, modify, or replace, GIS products without notification. For more information contact:
Superior Ranger District
209 West Riverside
Superior, MT 59872

8/12/2014 12:24 PM T:\FS\NFS\Lolo\Project\Superior\NEPACedarThom\GIS\Data\CedarThomFEIS\DecisionMap.mxd Dpj